



FELLESTADET FOR DET SOERLIGE
c/o NORWEGIAN PEOPLES'S AID
P.O. BOX 3381
DAR ES SALAAM

NPA-DSM.
J. No: 525
DATE 15/6/88

Main Office:
Bygdøy Allé 5
0257 Oslo 2, Norway
Tel.: (02) 56 56 90/5
International call: +47 2 56 56 90/5
Telex: 19361 Nplan N

ATT: MR K. MEKKI

Your ref.:

Our ref.: T024/NT207/88/CWG/jm

DSM.1988.06.15

Dear Sir,

RE: T024. SUPERVISION OF ANC HOUSE AT KURASINI PLOT 28


Having visited the site today we observed that the window frames that were fabricated at Mazimbu are being placed in old Building 1.

In connection with the above, we wish to recommend that:

- (a) Hold fasts screwed or nailed to window and door frames jambs to ensure proper fixing of the frames.
- (b) Precast concrete sills be used for all external windows and/or galvanized M.S. "water bar" to prevent water seeping in under the window frames.

Thanking you we remain

Yours faithfully,
for NORPLAN A/S (T) BRANCH



C.W. GOMES
PROJECTS ENGINEER

NORPLAN
TANZANIA BRANCH
P.O. BOX 2820
DAR ES SALAAM
TANZANIA

c.c Mr. K. Ekeberg , NORPLAN Oslo.