LuM/038/0053/02

Malune.

LORENZ & NDILILA, ARCHITECTS
LONGACRES OFFICE
P.O. Box 50079
LUSAKA

	LUSAKA		
8720	STAR FURNITURE FLATS, MWAYI ROAD		
No. 15	MINUTES OF PROJECT MEETING No. 15 HELD ON WEDNEST 10TH JANUARY, 1990 AT 14.30 HOURS ON SITE	DAY	
	Present: Messrs. B. Silungwe Minestone (Z) Ltd. "J. Mutale """" "K. Chirwa """" "A. Nchindila ZMCK Consulting E. "E. Mulube """ "I. Ndilila Lorenz & Ndilila, Apologies: Messrs. Banda ZMCK Consulting E.	nginee " Archit	ects
15.1.00	MINUTES OF PREVIOUS MEETING	ACT.	A.I.
15.1.01	Minutes of previous meeting were agreed.		
15.2.00	OUTSTANDING ITEMS FROM PREVIOUS MEETING		
15.2.01	Hot Water System (14.2.01 refers)		
	Minestone to inform about cost of geysers from Botswana as well as cost of piping, valves and any other related fittings.	MZI:	
15.2.02	Hose Reels (14.2.02 refers)		
	Mrs. Ndilila said that Mr. Patel of the ZMCK Botswana Office advised on wrong direction of one of the valves. Drawing is to be reissued accordingly. Mrs. Ndilila informed that detail drawing for	ZMCK	
	full hose reel enclosure will be ready by end of this week.	L&N	
c)	Mr. Silungwe said that Hose reels have meanwhile been procured from Roan Construction.		
	Temporary ZESCO Connection (14.2.03 refers)		
a)	Mr. Silungwe reported that connections is still outstanding.	THUN	D
15.2.04	Balcony Lintol (14.2.04 refers) No confirmation on quantity of steel used as given by Minestone available from Q.S.	PRP	
15.2.05	Plaster (14.2.05 refers) Recommended mix for further sample preparation to external plaster defered.	L&N	
15.2.06	Aluminium Windows (14.2.06 refers) Clarification on which gaskets (glazing strips or insulation strips between frame and sash)the was referring to was not available. However the windows were already on site.	suppl	ier
15.2.07	Window Openings (14.2.07 refers)		
	Mr. Chirwa said that lintols will be corrected during the process of fitting the windows.	MZL	

15.2.08 Shortages (14.2.08 refers)

Mr. Chirwa reported that the cement supply is still erratic, but crushed stone has meanwhile been obtained. Presently the supply of riversand is problematic.

15.2.09 Kitchen Cupboards (14.2.09 refers) Clients decision on possible closedown of their workshop or shifting of operation awaited. STARE Mr. Silungwe reported that the sinktops have arrived and could be supplied to the client on request for the sample preparation.

MZL

15.2.10 Site Inspection (14.2.11 refers)

Mr. Chirwa said that Thunderbolt has done some rectifications to the electrical works. Mr. Silungwe suggested and it was agreed to carry out the inspection immediately after next project ZMCK L&N meeting.

15.2.11 Roof reinforcement to Sub-station Mrs. Ndilila said that the Q.S. has meanwhile been supplied with a copy of the standard sub-station drawing. The Q.S. to treat the roof reinforcement as a variation. PRP

15.2.12 Quality Control (14.4.02 refers) Mr. Silungwe said that Wade Adams has been requested to supply photocopies of the results with missing information filled in. Contractor to follow up.

MZL

15.2.13 Imported Reinforcement Steel

Mrs. Ndilila said that the letter from the Q.S. dated 3rd January, 1990 has been received and confirms that the quantity of the first 3 consignments received is within the project requirements. Mr. Silungwe confirmed that 2 consignments so far have been signed for by the client.

15.3.00 PROGRESS

15.3.01 Contractor's progress report was handed over and a copy of it is attached to the minutes.

15.4.00 MATTERS ARISING

15.4.01 Water Supply Pipes

Mr. Silungwe said that the length of the required water supply pipe of 65 mm diameter is now increased compared to the original contract. He expressed that the importation of more pieces! might delay the project and therefore intends to obtain them locally from Suppliers who import them in 75 mm diameter. Mrs. Ndilila requested the Contractor to measure the additional length required and obtain quotations from suppliers for the Engineers and Quantity Surveyors approval.

MZL

15.5.00 NEXT MEETING

15.5.01 The next project meeting shall be held on Wednesday 24th January, 1990 at 14.30 hours on site.

LORENZ & NDILILA, ARCHITECTS.

Distribution:

Client	3
Minestone (Z) Ltd.	3
ZMCK Consulting Engineers	3
Teter Richards & Partners	2
Thunderbolt Electr. Ltd.	1
Architect's File	2

PROGRESS REPORT	FOR	MA		
F/F. STAIREASES 100%	Con Advertise Inc. of			
G/F CEILIMG PLASTER				
G/F THTERNAL PLASTER	952			
S/F BRICKWORK	60%			
100 mm A/a pres	60%			
G. I. WATER PIPES	30%			
MANHOLE BENCHING	85			
SEWERLINE	75	%		
BLOCK 2				
S/F SLAB	1 o			
F/F STAIRCASES	9	8 %		
	建 . 4. 3. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.			

G/F INTERNAL PLASTERING 65%
(WALLS)

G/F CEILING PLASTER GOZ

GI WATER PIPES 25%

PUMP HOUSE SUBSTRUCTURE LONG CONC. WORK 95%

SURSTRUCTURE 1009
BRICHUSORK 1556

White the text of the second o